



NOTES:

*1 - Some sensors require a load resistor, check with your manufacture.

PPO2.COM		Schematic diagram of the one display three sensor PPO2 board			
WWW.PPO2.COM		SIZE A	DWG. By: Mark Munro	DWG NO.: 1_3shem.dwg	REV 0
http://www.ppo2.com/files/		Date: 4/25/00	SHEET: 1 OF 1		