



**NOTES:**

\*1 - Some sensors require a load resistor, check with your sensor manufacturer

<b>PPO2.COM</b>		Schematic diagram of the one display one sensor PPO2 board			
WWW.PPO2.COM		SIZE A	DWG. By: Mark Munro	DWG NO.: 1_shem.dwg	REV 0
http:\\www.ppo2.com\\files\\		Date: 4/25/00	SHEET: 1 OF 1		