



NOTES:

*1 - Some sensors require a load resistor, check with your manufacture.

PPO2.COM		Schematic diagram of the three display three sensor PPO2 board			
WWW.PPO2.COM		SIZE A	DWG. By: Mark Munro	DWG NO.: 3_shem.dwg	REV 0
http:\\www.ppo2.com\\files\\		Date: 4/11/00	SHEET: 1 OF 1		